

Annexure D

BUILDING SAFETY CERTIFICATE

No. **1275/HYD/2025**

Dated: **12-02-2025**

I hereby Certified that the existing building **SRI SAI MODEL HIGH SCHOOL** (name of the building or premises) at, **H.NO: 2-1-7/2, Pedda cherlapally, Kapra Mandal, Medchal Malkajgiri District. Telangana** (address) is having block(s) / Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	GROUND , FIRST & SECOND FLOORS					

The building is owned/occupied by **SRI SAI MODEL HIGH SCHOOL** Situated at **H.NO: 2-1-7/2, Pedda cherlapally, Kapra Mandal, Medchal Malkajgiri District. Telangana** have complied with the Building Safety Requirements in accordance with National Building code Rules, and verified by the officers concerned of (N.Venkata Ramana Rao Structural Engineer approved by GHMC Hyderabad) on **11-02-2025** in the presence of **Principal (G. NAVEEN REDDY)** and that the building/premises is fit for occupancy for running school with effect from (**2025-2026**) to **(2035-2036)** for a period of **Ten years** in accordance. with rule and subject to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
2. Should Procure Fire Safety Certificate from Fire Dept their recommendations should be followed and updated regularly.
3. Original Documents of the Building should be kept safety

Issued on **12-02-2025** at Hyderabad. by.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



N. Venkata Ramana Rao

Signature with Seal: **Lic. No. 19/Strl. Engineer/TP10/GHMC/2024-29**
Plot No 2, G Block, A.S Rao Nagar, Kapra, Hyd

Name: **N.VENKATARAMANA RAO**

Designation: **Structural Engineer**

Name & Address of Department/ Office: **GHMC Hyderabad.**